

**Spreenauten.de**  
**Spreenauten**  
**Radio Technology (DMR,**  
**TETRA, ATEX, WLAN & 5G)**

- > DMR Radio Technology
- > Two-way Radios
- > TETRA Radios & Radio Cells
- > Atex Radios
- > Battery & Charging
- > Technology for Radios
- > Headsets & Loudspeaker
- > Microphones
- > WLAN - Wireless LAN as
- > MESH-LAN & conservative
- > WIFI
- > DECT Phones & Repeaters
- > (Base Stations)
- > Tour Guide systems
- > Antennas & Antenna
- > Technology
- > 5G

**Motorola & Hytera**  
**Service**  
**Radio technology**  
**Applications**

**Spreenauten GmbH**  
Meeraner Str. 11b  
12681 Berlin. Germany

**Phone**  
+49.(0)30.293.8197-0

**Toll-free international**  
00800.11.88.44.00

**Fax**  
+49.(0)30.293.8197-0

**E-mail**  
support@spreenauten.com

**Website**  
www.spreenauten.de

**HRB**  
AG Berlin-Charlottenburg  
136729B

**UST-ID Deutschland**  
DE279088233

Hytera DMR Update 9.2 is available for  
News > download

<https://www.spreenauten.com/funktechnik-news/20-04-2020/hytera-dmr-update-9-2-download>

Posted on 20/04/2020 11:52



After SpectraLink, Hytera today also delights us with an overdue update for numerous Hytera DMR radios. The update has the version number 9.2. and is now available for download.

Also available for download is DMR software version 7.7 for Hytera's PD5 series.

But let Hytera have its say:

"Ladies and gentlemen,  
we very much hope that you and your family are well, that you are healthy and that you can derive positive impulses and developments for the future from the current crisis mode.

After a few uncertain weeks, we were largely able to return to a certain normality in our working life and therefore make the new DMR software release 9.2 available for download only a little later than planned.

DMR software release 9.2 fixes some software errors that can be found in the release note.

In addition, the structure of the software has been greatly simplified. In contrast to Release 9.0, there is now only one firmware and CPS version for repeaters, radios and the PD5 series"

And here the promised download links:

**DMR Software Release 9.2 for the PD6, PD7 and X1 series as well as for the PD985, MD655, MD7 series and repeaters of the RDXXX series**

- DMR\_SW\_CPS\_V9.00.09.306.iM(EMS) for subscribers
- DMR\_TerminalBatchUpgrade\_Repeater\_TO\_V9.02.01.004.iM
- DMR\_TerminalBatchUpgrade\_Subscribe\_TO\_V9.02.01.013.iM
- Documents

Download link: [Download Hytera DMR Software Release 9.2](#)

### **DMR software version 7.7 for the PD5 series**

- DMR PDS UPGRADEKIT SUBSCRIBE TO V7.07.01.004.iM
- DMR\_SW \_ CPS\_ V9.00.09.300(EB-EM5)
- PD50X&PD56X Radio\_Release Notes\_R7.7\_V1.0.pdf

Download link: [Download Hytera DMR software version 7.7 for the PD5 series](#)